

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403051496

Date Received:
05/17/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Romana Cowden

720-951-5895

cogcc.inspections@caerusoilandgas.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696203624

Inspection Date: 05/02/2022

FIR Submit Date: 05/04/2022

FIR Status: _____

Inspected Operator Information:

Company Name: CAERUS PICEANCE LLC

Company Number: 10456

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 334983

Location Name: Federal Multi Well Number: 28-5BB (PA-29) County: _____

Qtrqtr: Lot 1 Sec: 29 Twp: 7S Range: 95W Meridian: 6

Latitude: 39.412550 Longitude: -108.015790

FACILITY - API Number: 05-045- -00 Facility ID: 334983

Facility Name: Federal Multi Well Number: 28-5BB (PA-29)

Qtrqtr: Lot 1 Sec: 29 Twp: 7S Range: 95W Meridian: 6

Latitude: 39.412550 Longitude: -108.015790

CORRECTIVE ACTIONS:

1 ☒ CA# 161561

Corrective Action: Comply with Rule 606.a

Date: 05/11/2022

Response: CA COMPLETED

Date of Completion: 05/11/2022

Operator
Comment: Removed.

COGCC Decision: Approved pending re-inspection

COGCC Representative:	Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. Operator has provided no documentation attached to this resolution to show work has been conducted per corrective action(s). A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.
-----------------------	--

2  CA# 161562

Comply with 1002.f.; install or repair BMPs per good engineering practices, and maintain in proper functioning condition.

Date: 05/11/2022

Response: CA COMPLETED

Date of Completion: 05/11/2022

Graded pad surface, repaired and seeded erosion

COGCC Decision: Approved pending re-inspection

COGCC Representative:	Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. Operator has provided no documentation attached to this resolution to show work has been conducted per corrective action(s). A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.
-----------------------	--

OPERATOR COMMENT AND SUBMITTAL

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Romana Cowden

Signed:

Title: EHS

Date: 5/17/2022 10:35:32 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403051496	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files