

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403051518

Date Received:
05/17/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
Romana Cowden	720-951-5895	cogcc.inspections@caerusoilandgas.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696203608

Inspection Date: 05/02/2022

FIR Submit Date: 05/03/2022

FIR Status: _____

Inspected Operator Information:

Company Name: CAERUS PICEANCE LLC

Company Number: 10456

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 334752

Location Name: FEDERAL-67S95W Number: 30NWNW County: _____

Qtrqr: NWN Sec: 30 Twp: 7S Range: 95W Meridian: 6
W

Latitude: 39.412490 Longitude: -108.045110

FACILITY - API Number: 05-045- -00 Facility ID: 334752

Facility Name: FEDERAL-67S95W Number: 30NWNW

Qtrqr: NWN Sec: 30 Twp: 7S Range: 95W Meridian: 6
W

Latitude: 39.412490 Longitude: -108.045110

CORRECTIVE ACTIONS:

1 CA# 161517

Corrective Action: Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition

Date: 05/04/2022

Response: CA COMPLETED

Date of Completion: 05/02/2022

Operator Comment: Route Pumper Tightened Valve stopping leak.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. Operator has provided no documentation attached to this resolution to show work has been conducted per corrective action(s). A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

2 CA# 161518

Corrective Action: Clean and properly dispose in accordance with 905 rules.

Date: 06/03/2022

Response: CA COMPLETED

Date of Completion: 05/03/2022

Operator Comment: Impacted material has been removed from location and properly disposed of.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. Operator has provided no documentation attached to this resolution to show work has been conducted per corrective action(s). A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

3 CA# 161519

Corrective Action: Install or repair required BMPs and maintain per Rule 1002.f.(2)C

Date: 05/10/2022

Response: CA COMPLETED

Date of Completion: 05/02/2022

Operator Comment: Disturbance on location is from Summit Midstream, NOT associated with Caerus.

COGCC Decision: **Not Approved**

COGCC Representative: Areas identified within inspection and photo documentation are within the disturbance and interim areas of Caerus' Location- Caerus remains responsible for the management of the Location, until the site receives a passing final inspection.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Romana Cowden

Signed: _____

Title: EHS

Date: 5/17/2022 10:43:40 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

403051518	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files