

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/31/2022

Submitted Date:

06/07/2022

Document Number:

688000643**FIELD INSPECTION FORM**Loc ID 317538 Inspector Name: YOUNG, ROB On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 7800Name of Operator: BEREN CORPORATIONAddress: 2020 N BRAMBLEWOOD STREETCity: WICHITA State: KS Zip: 67206**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kay, Michael	316-249-7597	kaym@berexco.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
239260	WELL	TA	12/01/1974	OW	123-07047	MOYER UNIT 13-32	EI

General Comment:

Environmental inspection related to Rem #22342. Deadman anchors on location require removal and recontouring prior to requesting project closure. Cement washout on the southeast side of the wellhead requires removal and proper disposal, contact the flowline group for flowline abandonment requirements.

Environmental**Spill/Remediation:**

Comment: [Contact flowline group for flowline abandonment requirements. Wellhead excavations should not be backfilled until any flowline abandonment requirements have been met.](#)

Corrective Action: [Provide documentation of compliance with flowline abandonment rules.](#)

Date: 06/28/2022

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688000644	Location photographs	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5773387