

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403074296

Date Received:

06/09/2022

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10766

Name of Operator: ARKOMA OPERATIONS LLC

Address: 2121 S COLUMBIA AVE SUITE 101

City: TULSA State: OK Zip: 74114

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Price, Andrew

918-260-8324

aprice@arkomaops.com

Labowskie, Steve

steve.labowskie@state.co.us

Engineering

dnr_cogccengineering@state.co.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 702500061

Inspection Date: 04/21/2022

FIR Submit Date: 06/01/2022

FIR Status: _____

Inspected Operator Information:

Company Name: ARKOMA OPERATIONS LLC

Company Number: 10766

Address: 2121 S COLUMBIA AVE SUITE 101

City: TULSA State: OK Zip: 74114

LOCATION - Location ID: 311925

Location Name: IGE-N33N8W

Number: 16NENE

County: LA PLATA

Qtrqr: NENE

Sec: 16

Twp: 33N

Range: 8W

Meridian: N

Latitude: 37.108540

Longitude: -107.717660

FACILITY - API Number: 05-067-

-00

Facility ID: 270215

Facility Name: SEMLER

Number: 2

Qtrqr: NENE

Sec: 16

Twp: 33N

Range: 8W

Meridian: N

Latitude: 37.108540

Longitude: -107.717660

CORRECTIVE ACTIONS:

1 CA# 162376

Corrective Action: Apply Out of Service Locked and Tagged on unused flow line per rule 1101.(3)

Date: 06/02/2022

Response: CA COMPLETED

Date of Completion: 06/02/2022

Operator Comment: Applied locks and tags on all the unused flow lines.

COGCC Decision: _____

COGCC
Representative:

2 CA# 162378

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 06/16/2022

Response: CA COMPLETED

Date of Completion: 06/09/2022

Operator
Comment:

Repaired the erosion on the nothwest end of location.

COGCC Decision: _____

COGCC
Representative:

3 CA# 162514

Corrective Action: Submit Form 7 to correctly reprot well status as Temporarily Abandoned per rule 434.b.

Date: 07/02/2022

Submit Form 4 Sundry Notice as directed per rule 434.b.

Response: CA COMPLETED

Date of Completion: 06/02/2022

Operator
Comment:

Submitted Form 4 (Doc ID 403066545) to report that the Semler 2 is TA'd. The status on the next submitted Form 7 will now show the status as TA'd.

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jaime Pugh

Signed: _____

Title: Engineering Analyst

Date: 6/9/2022 3:23:46 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403074305	(702500061) description corrections with after photos
-----------	---

Total Attach: 1 Files