

FORM

42

Rev
01/21

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



OGCC RECEPTION

Receive Date:

06/11/2022

Document Number:

403076047

FIELD OPERATIONS NOTICE

The Form 42 shall be submitted as required by Rule, Notice to Operators, Policy, or Condition of Approval.
A Form 42 Update shall be submitted to revise the scheduled date or time on a previous Form 42 - Advance Notice of Field Operations.
A Form 42 Update must be for the same well, location, or facility and for the same Field Operation as a previous Form 42.
NOTE: Operator's Contact for Advance Notices of Field Operations should be available 24 hours a day, 7 days a week and should have the most current scheduling information for the operation. Operator's Contact for other notices should be able to respond to questions regarding the reported information.

Update of a previous Form 42 Notice YES

Entity Information

OGCC Operator Number: 10518Contact Person: Bryan OlmsteadCompany Name: CONFLUENCE DJ LLCPhone: (719) 680-0497Address: 1125 17TH STREET #1550Fax: (303) 226-9595City: DENVER State: CO Zip: 80202Email: bolmstead@confluencelp.comAPI #: 05 - -Facility ID: 442024Location ID: 442024Facility Name: Middlepark 18☐ Submit By Other OperatorSec: 18Twp: 4NRange: 62WQtrQtr: SESWLat: 40.306280 Long: -104.371130

NOTICE OF MOVE-IN, RIG-UP

Start Date: 06/11/2022 Time: 18:00 (HH:MM)

Select the type of rig below. (Only 1 box may be checked)

☒ Drilling Rig (Spud Rig) – 2 Business Days Notice☐ Drilling Rig – 2 Business Days Notice☐ Work-Over Rig, Planned Operations – 2 Business Days Notice☐ Work-Over Rig, Unplanned Operations – notify within 1 Business Day after startIs the estimated duration of operations with this rig on this Location anticipated to last for longer than one day? Yes

If YES, describe the estimated anticipated duration of these operations:

This is an update to the Form 42 submitted on 6/4/22, Doc # 403068044. The prior rig Confluence intended to set surface casings on the subject location was Ensign 122. When it was mobilized to location, a crack was found in the substructure and it was determined to be unusable for this operation. White Mountain 454 will be drilling surface casings in its place, thus the late notice. Apologies! Drilling these 19 surface casings is estimated to take 16 days, from 6/11-6/27/2022.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct and complete.

Print Name: Brittany RotheEmail: brothe@confluencelp.com

Signature: _____

Title: Engineering ManagerDate: 06/11/2022