

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/13/2022

Submitted Date:

06/13/2022

Document Number:

699105566

FIELD INSPECTION FORMLoc ID 452874 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 8960

Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY

Address: 410 17TH STREET SUITE #1400

City: DENVER State: CO Zip: 80202

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
452875	WELL	SI	11/01/2021	OW	123-45804	Mustang V41-27-28XRLNB	SI

General Comment:

This is a follow up inspection to FIRR #403041105. CA's did not meet expectations

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unused equipment in multiple spots needs to be removed for good housekeeping. See attached photos		
Corrective Action:	Comply with Rule 606.	Date:	05/06/2022
Type	UNUSED EQUIPMENT		
Comment:	Unused production tanks need to be removed for good housekeeping. See attached photo.		
Corrective Action:	Comply with Rule 606.	Date:	05/27/2022
Type	TRASH		
Comment:	Trash in multiple spots needs to be removed for good housekeeping. See attached photos.		
Corrective Action:	Comply with Rule 606.	Date:	05/06/2022

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL					,
Comment:					
Corrective Action:					Date:

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Inadequate	Walls Insufficient	Base Sufficient	Inadequate
Comment:	Repair/ Install metal berms around production tanks. See attached photo.			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 912.d.(1).			Date: 05/13/2022

Venting:

Yes/No	NO		
--------	----	--	--

Comment:			
Corrective Action:		Date:	
<u>Flaring:</u>			
Type			
Comment:			
Corrective Action:		Date:	

Type			
Comment:			
Corrective Action:		Date:	

Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 452875 Type: WELL API Number: 123-45804 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: si

Corrective Action: _____

Date: _____

BradenHeadDate of Last Brhd Test: 04/12/2022Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0

Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____

Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Monday 6/13/22 at approximately 0809hrs, I, Inspector Adam Burns, Conducted an on-site inspection to FIRR #403041105 at Mustang V41-27-28XRLNB of Civitas, at</p> <p>Location ID # 452874 in Weld County, Colorado.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Unused equipment in multiple spots needs to be removed for good housekeeping. Comply with Rule 606. With a corrective action date of 5/6/22</p> <p>Trash in multiple spots needs to be removed for good housekeeping. Comply with Rule 606. With a corrective action date of 5/6/22</p> <p>Unused production tanks need to be removed for good housekeeping. Comply with Rule 606. With a corrective action date of 5/27/22</p> <p>Repair/ Install metal berms around production tanks. Repair or install berms or other secondary containment devices per Rule 912.d.(1). With a corrective action date of 5/13/22</p> <p>See attached photos.</p> <p>Submit pictures on FIRR.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	burnsa	06/13/2022

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699105567	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5778324