

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/08/2022

Submitted Date:

06/14/2022

Document Number:

700704306

FIELD INSPECTION FORM

 Loc ID _____ Inspector Name: _____ On-Site Inspection
 314500 _____ Ramsey, Scott _____ 2A Doc Num: _____
Operator Information:
 OGCC Operator Number: 16700
 Name of Operator: CHEVRON USA INC
 Address: 760 HORIZON DRIVE STE 401
 City: GRAND JUNCTION State: CO Zip: 81506
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 10 Number of Comments
 2 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
, Chevron	970-257-6019	cnoc@chevron.com	ALCR
, Chevron	970-257-6004	andrewolson@chevron.com	Operations Superintendent
, Chevron	970-257-6079	stephaniebittner@chevron.com	Admin/Reg Tech
, Chevron	661-437-8040	rpuechner@chevron.com	Decommissioning

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
228864	WELL	SI	07/01/2020	OW	103-05855	WILSON CREEK UNIT 57	TA

General Comment:**COGCC Inspection Report Summary**

On Wednesday 6/8/2022 at approximately 1100, I, Inspector Scott Ramsey, conducted a routine inspection at Chevron Wilson creek 57, at Location # 314500 in Rio Blanco county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management.

During this inspection the following possible compliance issues were observed:

1. Stored equipment (Trailers)
2. No well head signage.

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	No well head signage.		
Corrective Action:	Provide proper signage untill well is cut off.	Date:	07/26/2022
Type	OTHER		
Comment:	Entrance signage		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	_____
Corrective Action:	<input type="text"/>		

Good Housekeeping:

Type	STORAGE OF SUPL		
Comment:	Stored equipment (Trailers)		
Corrective Action:	Remove stored equipment	Date:	09/06/2022

Overall Good:

Spills:

Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type			corrective date
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Well head		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 228864 Type: WELL API Number: 103-05855 Status: SI Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700704312	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5779428