

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
403080036

Date Received:  
06/15/2022

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
Romana Cowden	720-951-5895	cogcc.inspections@caerusoilandgas.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 702800153

Inspection Date: 04/21/2022

FIR Submit Date: 04/26/2022

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: CAERUS PICEANCE LLC

Company Number: 10456

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 335228

Location Name: BENZEL DISPOSAL-66S93W Number: 36NWNE County: \_\_\_\_\_

Qtrqr: NWNE Sec: 36 Twp: 6S Range: 93W Meridian: 6

Latitude: 39.488510 Longitude: -107.721330

FACILITY - API Number: 05-045- -00 Facility ID: 335228

Facility Name: BENZEL DISPOSAL-66S93W Number: 36NWNE

Qtrqr: NWNE Sec: 36 Twp: 6S Range: 93W Meridian: 6

Latitude: 39.488510 Longitude: -107.721330

CORRECTIVE ACTIONS:

1 CA# 161289

Corrective Action: Corrective Action #1: Conduct weed management to prevent further establishment and spread of noxious weeds in accordance with Rule 1003.f by 5/26/2022. Ongoing weed management is required until location passes final reclamation.

Date: 05/26/2022

Corrective Action #2: In accordance with Rule 1003; Remove unused concrete forms and reduce and reclaim areas no longer needed for production, including, but not limited to areas at the southeast of the pad, surrounding the concrete forms. Reclamation activities shall be completed no later than 5/26/2022.

Corrective Action #3: Address subsidence occurring in the eastern interim areas of the Location in accordance with Rules 1003 and 602.c. by 5/26/2022.

Response: CA COMPLETED

Date of Completion: 06/09/2022

Operator Comment: Removed concrete forms. NOTE: Holy Cross has a concrete electrical vault in place and it is in use. Also filled subsidence and graded pad surface, and weeds were treated.

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

**OPERATOR COMMENT AND SUBMITTAL**

Comment: \_\_\_\_\_

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Romana Cowden Signed: \_\_\_\_\_

Title: EHS Date: 6/15/2022 10:06:38 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<b><u>Document Number</u></b>	<b><u>Description</u></b>

Total Attach: 0 Files