

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403080942

Date Received:

06/15/2022

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 3 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Victoria Dizghinjili

Phone

303-825-4822

Email

vdizghinjili@kpk.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 699503970

Inspection Date: 05/18/2022

FIR Submit Date: 05/19/2022

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: KP KAUFFMAN COMPANY INC

Company Number: 46290

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 320122

Location Name: PILAND-63S64W Number: 12NESW County: ADAMS

Qtrqr: NESW Sec: 12 Twp: 3S Range: 64W Meridian: 6

Latitude: 39.801720 Longitude: -104.501160

FACILITY - API Number: 05-001-

-00

Facility ID: 202740

Facility Name: PILAND

Number: 23-12

Qtrqr: NESW Sec: 12 Twp: 3S Range: 64W Meridian: 6

Latitude: 39.801720 Longitude: -104.501160

CORRECTIVE ACTIONS:

2 CA# 162074

Corrective Action: Location is within a designated setback location, repair or install berms or other secondary containment devices per Rule 604.c.(2)G.6/5/22

Date: 06/05/2022

Response: CA COMPLETED

Date of Completion: 06/05/2022

Operator  
Comment:

All berms at location have been repaired. Please see attached pictures.

COGCC Decision:

--

--

Date: 6/15/2022 3:21:14 PM

403080963	Updated sign PIC1
403080967	Berms repaired PIC2

Page 2 of 2