

Streeter Fed 2

Document number 693904486

Date completed 6/2/2022

Repaired existing rock run out and added wattles

Established additional runout



Cleaned out drainage ditch around location and added wattles

