

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/13/2022

Submitted Date:

06/13/2022

Document Number:

699105566

FIELD INSPECTION FORM

Loc ID 452874 Inspector Name: Burns, Adam On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 8960
Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY
Address: 410 17TH STREET SUITE #1400
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 8 Number of Comments
4 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
452875	WELL	SI	11/01/2021	OW	123-45804	Mustang V41-27-28XRLNB	SI

General Comment:

This is a follow up inspection to FIRR #403041105. CA's did not meet expectations

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unused equipment in multiple spots needs to be removed for good housekeeping. See attached photos		
Corrective Action:	Comply with Rule 606.	Date:	05/06/2022
Type	TRASH		
Comment:	Trash in multiple spots needs to be removed for good housekeeping. See attached photos.		
Corrective Action:	Comply with Rule 606.	Date:	05/06/2022
Type	UNUSED EQUIPMENT		
Comment:	Unused production tanks need to be removed for good housekeeping. See attached photo.		
Corrective Action:	Comply with Rule 606.	Date:	05/27/2022

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL					
Comment:	<input type="text"/>				
Corrective Action:	<input type="text"/>				Date:

Paint

Condition	<input type="text"/>
Other (Content)	<input type="text"/>
Other (Capacity)	<input type="text"/>
Other (Type)	<input type="text"/>

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Inadequate	Walls Insufficient	Base Sufficient	Inadequate
Comment:	Repair/ Install metal berms around production tanks. See attached photo.			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 912.d.(1).			Date:

Venting:

Yes/No	NO		
--------	----	--	--

Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 452875 Type: WELL API Number: 123-45804 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

BradenHead

Date of Last Brhd Test: 04/12/2022 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action: Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Monday 6/13/22 at approximately 0809hrs, I, Inspector Adam Burns, Conducted an on-site inspection to FIRR #403041105 at Mustang V41-27-28XRLNB of Civitas, at Location ID # 452874 in Weld County, Colorado. During this inspection the following possible compliance issues were observed: Unused equipment in multiple spots needs to be removed for good housekeeping. Comply with Rule 606. With a corrective action date of 5/6/22 Trash in multiple spots needs to be removed for good housekeeping. Comply with Rule 606. With a corrective action date of 5/6/22 Unused production tanks need to be removed for good housekeeping. Comply with Rule 606. With a corrective action date of 5/27/22 Repair/ Install metal berms around production tanks. Repair or install berms or other secondary containment devices per Rule 912.d.(1). With a corrective action date of 5/13/22 See attached photos. Submit pictures on FIRR. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	burnsa	06/13/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403077587	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5778339
699105567	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5778324