

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/22/2022

Submitted Date:

06/22/2022

Document Number:

679604803**FIELD INSPECTION FORM**Loc ID 457767 Inspector Name: Santistevan, Brittani On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10671Name of Operator: EDGE ENERGY II LLCAddress: 600 12TH STREET SUITE 115City: GOLDEN State: CO Zip: 80401**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Turner, Ben		bturner@edgeenergy1.com	Engineering; All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
457766	WELL	PR	08/01/2020	OW	123-48072	Simpson 36-1H	PR

General Comment:

Location

Overall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Water tanks do not display BBLs. See attached photos.		
Corrective Action:	Install sign to comply with Rule 605.h.		Date: 07/22/2022
Type	BATTERY		
Comment:	Adequate		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:			Date:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Stained soil at wellhead and compressor; standing oil on skid. See attached photos		
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and review self inspection processes per Rule 1002.(2).d.		Date: 07/22/2022
Type	STORAGE OF SUPL		
Comment:	Unused equipment at compressor and near wellhead. See attached photos.		
Corrective Action:	Comply with Rule 606.		Date: 07/22/2022

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type			
Comment:			
Corrective Action:			Date:

Equipment:			corrective date
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:

Type: Compressor	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	OTHER	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	UNKNOWN	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares containment with crude oil tanks			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	4	400 BBLs	STEEL AST		,	
Comment:	Anchored					
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				

Inspected Facilities				
Facility ID: 457766	Type: WELL	API Number: 123-48072	Status: PR	Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:				Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment:

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary **Weather Conditions: cloudy, dry ground On Wednesday, June 22, 2022 at approximately 14:30, I, Inspector Brittani Santistevan, conducted an on-site inspection at SIMPSON 36-1H (Edge Energy II LLC), at location #: 457767 in WELD COUNTY Colorado. While there, I observed a producing facility. During this inspection the following possible compliance issues were observed:</p> <ol style="list-style-type: none"> 1. Unused equipment at chemical barrel near wellhead and at compressor. Remove to comply with Rule 606. (Corrective Action Date: July 22, 2022) See attached photo #5, 6. 2. Stained soil in various areas of location. Conduct maintenance on equipment, cleanup stained material and review self inspection processes per Rule 1002.(2).d. (Corrective Action Date: July 22, 0222) See attached photo #s: 1-4 3. Two water tanks do not display BBLS on tanks. Install sign to comply with Rule 605.h. (Corrective Action Date: July 22, 2022) See attached photo #: 7 <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	santistb	06/22/2022

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679604805	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5788565