

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403082516

Date Received:

06/16/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 16700

Name of Operator: CHEVRON USA INC

Address: 760 HORIZON DRIVE STE 401

City: GRAND JUNCTION State: CO Zip: 81506

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Olson, Andrew</u>		<u>AndrewOlson@chevron.com</u>
<u>O'Nan, Chester</u>		<u>CNOC@chevron.com</u>
<u>Bittner, Dawn</u>	<u>970-257-6079</u>	<u>stephaniebittner@chevron.com</u>
<u>Puechner, Rachel</u>		<u>RPuechner@chevron.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 702800180

Inspection Date: 05/06/2022

FIR Submit Date: 05/10/2022

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: CHEVRON USA INC

Company Number: 16700

Address: 760 HORIZON DRIVE STE 401

City: GRAND JUNCTION State: CO Zip: 81506

LOCATION - Location ID: 314510

Location Name: WILSON CREEK UNIT-63N94W Number: 34NENW County: \_\_\_\_\_

Qtrqtr: NENW Sec: 34 Twp: 3N Range: 94W Meridian: 6

Latitude: 40.190016 Longitude: -107.928068

FACILITY - API Number: 05-103- -00 Facility ID: 314510

Facility Name: WILSON CREEK UNIT-63N94W Number: 34NENW

Qtrqtr: NENW Sec: 34 Twp: 3N Range: 94W Meridian: 6

Latitude: 40.190016 Longitude: -107.928068

CORRECTIVE ACTIONS:

1 ☒ CA# 161729

Corrective Action: Comply with Rule 913.b.(5).B.i.

Date: 05/24/2022

Response: CA COMPLETED

Date of Completion: 05/16/2022

Operator Comment: Fence panel has been installed to completely enclose the excavation area. See attached pictures.  
This CA has been stated as complete by Inspector O'Malley in Inspection Document 702800263

COGCC Decision: Approved

COGCC Representative: This CA has been stated as complete by Inspector O'Malley in Inspection Document 702800263.

**2** ☒ CA# 161730

Corrective Action: Install or repair BMPs to enable egress from the excavated area.

Date: 05/12/2022

Response: CA COMPLETED

Date of Completion: 05/16/2022

Operator Comment: Excavation around wellhead is clean and the slope of the pit is sufficiently gentle to allow for wildlife egress. See attached pictures.  
This CA has been stated as complete by Inspector O'Malley in Inspection Document 702800263

COGCC Decision: Approved

COGCC Representative: This CA has been stated as complete by Inspector O'Malley in Inspection Document 702800263.

**3** ☒ CA# 161731

Corrective Action: Comply with Rule 913.b.(5).B.i-v.

Date: 05/12/2022

Response: CA COMPLETED

Date of Completion: 05/23/2022

Operator Comment: It was observed in Inspection Document 702800263 that a straw wattle has been installed around the perimeter of the soil pile. This corrective action has been addressed.  
Since that time the soil pile has been removed. See attached pictures.

COGCC Decision: Approved

COGCC Representative: It was observed in Inspection Document 702800263 that a straw wattle has been installed around the perimeter of the soil pile. This corrective action has been addressed.

**OPERATOR COMMENT AND SUBMITTAL**

Comment: All corrective actions have been completed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Dawn Bittner

Signed: \_\_\_\_\_

Title: Administrative Assistant

Date: 6/16/2022 4:26:27 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403082516	FIR RESOLUTION SUBMITTED
403082540	Corrective Action Photos

Total Attach: 2 Files