



**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 240949 Type: WELL API Number: 123-08737 Status: PR Insp. Status: PR

**BradenHead**

Date of Last Brhd Test: 05/18/2022 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_  
 End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Workover**

Comment:

Corrective Action:

Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary                      On Friday 7-8-2022 at approximately 1230 hrs. I, Inspector Robbie Revas,                      Conducted an on-site inspection: Inspection due to Notice Doc # 403099429                      Operator: KP Kauffman                      Location name: Lansons Farm #14                      API #05-123-08737                      County: Weld                      Weather: Clear.                      Location: .Dry.                      While there, I observed Workover Rig operation, Changing pump and rods at the time of                      inspection                      During this inspection, I observed no compliance issues:                      See attached photos.                      No follow up site inspection is needed to ensure that the addressed                      Compliance issues comply with COGCC rules.</p>	revasr	07/08/2022

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702400681	location pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5798652">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5798652</a>