

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403100530

Date Received:

07/11/2022

FIR RESOLUTION FORM

Overall Status:

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10133  
Name of Operator: HILCORP ENERGY COMPANY

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name Phone

Labowskie, Steve

General

Email

steve.labowskie@state.co.us

FarmingtonRegulatoryTechs@hilcorp.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 702500164

Inspection Date: 07/01/2022

FIR Submit Date: 07/05/2022

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY

Company Number: 10133

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

LOCATION - Location ID: 326147

Location Name: HUBER-LOBATO-N35N8W Number: 26SENW County: LA PLATA

Qtrqtr: SENW Sec: 26 Twp: 35N Range: 8W Meridian: N

Latitude: 37.276070 Longitude: -107.716310

FACILITY - API Number: 05-067-00 Facility ID: 215946

Facility Name: HUBER-LOBATO Number: 1-26

Qtrqtr: SENW Sec: 26 Twp: 35N Range: 8W Meridian: N

Latitude: 37.276070 Longitude: -107.716310

CORRECTIVE ACTIONS:

1 CA# 163066

Corrective Action: Remove impacted material and dispose of in approved manner per rule 906 and 1002.f.

Date: 07/19/2022

Response: CA COMPLETED

Date of Completion: 07/08/2022

Operator Comment: We remove and replaced all impacted soil as well as removed all illegally dumped construction debris on fill slope.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

2 CA# 163067

Corrective Action: Use or remove unused equipment per rule 606.

Date: 07/19/2022

Response: CA COMPLETED

Date of Completion: 07/08/2022

Operator  
Comment: All unused equipment and trash around the pump jack and location was hauled off.

COGCC Decision:

COGCC  
Representative:

3 CA# 163068

Corrective Action: Remove debris per rule 606.

Date: 07/19/2022

Response: CA COMPLETED

Date of Completion: 07/08/2022

Operator  
Comment: We remove and replaced all impacted soil as well as removed all illegally dumped construction debris on fill slope. All unused equipment and trash around the pump jack and location was hauled off.

COGCC Decision:

COGCC  
Representative:

4 CA# 163069

Corrective Action: Remove trash to comply with rule 606.

Date: 07/12/2022

Response: CA COMPLETED

Date of Completion: 07/08/2022

Operator  
Comment: We remove and replaced all impacted soil as well as removed all illegally dumped construction debris on fill slope. All unused equipment and trash around the pump jack and location was hauled off.

COGCC Decision:

COGCC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Priscilla Shorty

Signed:

Title: OperationsRegulatory Tech

Date: 7/11/2022 6:04:30 AM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403100532	Huber-Lobato 1-26_Resolved Photos

Total Attach: 1 Files