

Location

Overall Good:

Signs/Marker:

| | | | |
|--------------------|----------|--|-------|
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Emergency Contact Number:

| | | | |
|--------------------|----------|-------|--|
| Comment: | Adequate | Date: | |
| Corrective Action: | | | |

Good Housekeeping:

| | | | |
|--------------------|---|--|------------------|
| Type | WEEDS | | |
| Comment: | Weeds around well need to be removed for good housekeeping. See attached photos | | |
| Corrective Action: | Comply with Rule 606. | | Date: 07/22/2022 |

Overall Good:

Spills:

| Type | Area | Volume | | |
|------|------|--------|--|--|
|------|------|--------|--|--|

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

| | | | |
|--------------------|----------|--|-------|
| Type | WELLHEAD | | |
| Comment: | Panel | | |
| Corrective Action: | | | Date: |

Equipment:

| | | | |
|--------------------|----------------------------------|--|-----------------|
| Type: Bradenhead | # 1 | | corrective date |
| Comment: | Appears to be plumbed to surface | | |
| Corrective Action: | | | Date: |
| Type: Plunger Lift | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Venting:

| | | | |
|--------------------|----|--|-------|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Flaring:

| | | | |
|--------------------|--|--|-------|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Inspected Facilities

Facility ID: 459440 Type: WELL API Number: 123-48856 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 01/18/2022 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 5 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

COGCC Comments

| Comment | User | Date |
|--|--------|------------|
| <p>COGCC Inspection Report Summary On Monday 7/11/22 at approximately 1052hrs, I, Inspector Adam Burns, Conducted an on-site inspection at Becker D17-735 of Chevron, at API # 05-123-48856 in Weld County, Colorado. During this inspection the following possible compliance issues were observed: Weeds around well need to be removed for good housekeeping. Comply with Rule 606. With a corrective action date of 7/22/22 See attached photo. Submit pictures on FIRR. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p> | burnsa | 07/12/2022 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------|---|
| 699105705 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5800229 |