

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/11/2022

Submitted Date:

07/12/2022

Document Number:

699105706

FIELD INSPECTION FORM

Loc ID 459443 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 2001 16TH STREET SUITE 900

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

9 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
459447	WELL	PR	12/24/2021	OW	123-48861	Becker D17-725	PR

General Comment:

LocationOverall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	Adequate	
Corrective Action:		Date: _____

Good Housekeeping:

Type	TRASH		
Comment:	Trash next to the well needs to be removed for good housekeeping. See attached photos.		
Corrective Action:	Comply with Rule 606.	Date:	07/22/2022
Type	OTHER		
Comment:	Stained soil next to the well needs to be removed. See attached photo.		
Corrective Action:	"Properly dispose of oily waste in accordance with 905.e."	Date:	07/22/2022
Type	WEEDS		
Comment:	Weeds around well need to be removed for good housekeeping. See attached Photos		
Corrective Action:	Comply with Rule 606.	Date:	07/22/2022

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

Equipment:

Type: Plunger Lift	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			

Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 459447 Type: WELL API Number: 123-48861 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 01/18/2022

Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Monday 7/11/22 at approximately 1053hrs, I, Inspector Adam Burns, Conducted an on-site inspection at Becker D17-725 of Chevron, at API # 05-123-48861 in Weld County, Colorado.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Weeds around well need to be removed for good housekeeping. Comply with Rule 606. With a corrective action date of 7/22/22</p> <p>Trash next to the well needs to be removed for good housekeeping. Comply with Rule 606. With a corrective action date of 7/22/22</p> <p>Stained soil next to the well needs to be removed. "Properly dispose of oily waste in accordance with 905.e." With a corrective action date of 7/22/22</p> <p>See attached photo.</p> <p>Submit pictures on FIRR.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	burnsa	07/12/2022

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
699105707	Inspection Photos	http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5800230