



STATE OF COLORADO
OIL AND GAS CONSERVATION COMMISSION

DEPARTMENT OF NATURAL RESOURCES
SUITE 380 LOGAN TOWER BUILDING
1580 LOGAN STREET
DENVER, COLORADO 80203

WILLIAM R. SMITH
Director
DENNIS R. BICKNELL
Deputy Director

(303) 894-2100

ROY ROMER
Governor

January 26, 1990

Mr. Robert Vaclavik
Poncho Production Co.
10675 Hobbit Lane
Westminster, Colorado 80030

RE: UIC Inspection - Poncho Unit

Dear Sir:

As required by revised COGCC rule 319 (b), an injection well that has been shut-in for a period of two (2) years or has failed to prove mechanical integrity is required to be repaired and pressure tested or plugged and abandoned within six (6) months. Therefore, the following injection wells are required to be repaired (if applicable) and pressure tested or plugged and abandoned by July 25, 1990.

Poncho Unit 6: NWNE 34-3S-59W
Poncho Unit 7: NENW 3-4S-59W

If you should decide to test any well it must be done prior to the P&A deadline. In the interim, the wells are required to be physically disconnected from the flowline at the wellhead until pressure tested or plugged and abandoned. Notification must be given to the Commission prior to conducting any test so that we may have the opportunity to witness it.

If you have any questions feel free to contact me.

Very truly yours,

Larry Robbins
Petroleum Engineer

LR/mc

cc: Files
(#0445B)