



99999999

OIL & GAS CONSERVATION COMMISSION  
FIELD INSPECTION REPORT☒ NOTICE OF UNSATISFACTORY INSPECTION

NOV - 7 1996

1120 Lincoln Street, Suite 801  
Denver, CO 80203  
(303)894-2100☐ NOTICE OF SATISFACTORY INSPECTION

API No. 05- 1001 - 5073	LEASE NAME: Flader &				
LOCATION: SWNW 9-35-60W	OPERATOR: Tyler Roeluis				
DATE: 11-5-96	INSPECTOR: EBB				
Insp. Type: SR	Insp. Status: PA	PA: Y <input checked="" type="radio"/> N <input type="radio"/>	Pass/Fail: P <input checked="" type="radio"/> F <input type="radio"/>	Viol.: Y <input checked="" type="radio"/> N <input type="radio"/>	NOV: Y <input type="radio"/> N <input checked="" type="radio"/>

## INSPECTION ITEM

## COMMENTS

## INPUT

Well ID Signs (Rule 210)		
Pits (Reserve/Production) (Rule 902, 903, 904)		
Fences (Rule 604.C.(3), 1003.A)		
Tank Battery Equipment (Rule 604)		
Fire Walls/Berms/Dikes (Rule 604)		
General Housekeeping (Rule 603.G)		
Spills (Oil/Water) (Rule 908)		
Bradenhead (Rule 207)		
Drilling Well/Workover (Rule 315)		
Surface Rehabilitation (Rule 317)	Location not leveled, cellar open ✓ grassland / CRP? Only dirt	
Miscellaneous	Boards + gravel on site. Subject to Commission Penalties ✓	

CORRECTIVE ACTION REQUIRED: Close cellar, level site  
remove oil field gravel.

Date Corrective Action Required By: 12-5-96

Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.



00326358

White - File Green - Operator Canary - Well Site