

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403115565

Date Received:
07/25/2022

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 66561

Name of Operator: OXY USA INC

Address: PO BOX 173779

City: DENVER State: CO Zip: 80217-3779

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Eric Maestas

eric_maestas@oxy.com

NEWVILLE TONI

toni_newville@oxy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 690203058

Inspection Date: 06/16/2022

FIR Submit Date: 06/20/2022

FIR Status: _____

Inspected Operator Information:

Company Name: OXY USA INC

Company Number: 66561

Address: PO BOX 173779

City: DENVER State: CO Zip: 80217-3779

LOCATION - Location ID: _____

Location Name: _____ Number: _____ County: _____

Qtrqtr: NESE Sec: 15 Twp: 27S Range: 70W Meridian: 6

Latitude: 37.698300 Longitude: -105.198320

FACILITY - API Number: 05-055- -00 Facility ID: 442224

Facility Name: Origin Meter Station Number: _____

Qtrqtr: NESE Sec: 15 Twp: 27S Range: 70W Meridian: 6

Latitude: 37.698300 Longitude: -105.198320

CORRECTIVE ACTIONS:

1 CA# 162824

Corrective Action: Comply with Rule 1003.a. and 606.

Date: 07/01/2022

Response: CA COMPLETED

Date of Completion: 07/20/2022

Operator Comment: Area reclaimed and sand piles removed

COGCC Decision: _____

| | | | |
|-----------------------|--|--|--|
| COGCC Representative: | | | |
|-----------------------|--|--|--|

| | | | |
|-----------------------|-------------------|---|--------------------------------|
| 2 | CA# 162825 | | |
| Corrective Action: | | Comply with the 1003 interim reclamation rules. | Date: 07/01/2022 |
| Response: | | CA COMPLETED | Date of Completion: 07/20/2022 |
| Operator Comment: | | Area reclaimed | |
| COGCC Decision: _____ | | | |
| COGCC Representative: | | | |

| | | | |
|-----------------------|-------------------|--|--------------------------------|
| 3 | CA# 162826 | | |
| Corrective Action: | | Install or repair required BMPs per Rule 1002.f.(2)C | Date: 07/01/2022 |
| Response: | | CA COMPLETED | Date of Completion: 07/20/2022 |
| Operator Comment: | | Area reclaimed and installed wattles around disturbed areas that need BMPS | |
| COGCC Decision: _____ | | | |
| COGCC Representative: | | | |

| | |
|---|-----------------------------|
| <u>OPERATOR COMMENT AND SUBMITTAL</u> | |
| Comment: | Corrective Actions Complete |
| I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete. | |
| Print Name: Eric Maestas | Signed: _____ |
| Title: HSE Advisor | Date: 7/25/2022 2:55:34 PM |

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

| <u>Document Number</u> | <u>Description</u> |
|------------------------|--|
| 403115569 | Areas Reclaimed, Sand piles removed, BMPs in place |

Total Attach: 1 Files