

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/20/2022

Submitted Date:

08/11/2022

Document Number:

697504082**FIELD INSPECTION FORM**Loc ID 482275 Inspector Name: Binschus, Chris On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10518Name of Operator: CONFLUENCE DJ LLCAddress: 1125 17TH STREET #1550City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		bolmstead@confluencelp.com	
Edwardson, Dylan		dylan.edwardson@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
482606	WELL	AP	07/27/2022		123-51759	Bigfoot 11-13-3	CI
482607	WELL	AP	07/27/2022		123-51760	Bigfoot 11-12-2	CI
482608	WELL	AP	07/27/2022		123-51761	Bigfoot 11-9-2	CI
482609	WELL	AP	07/27/2022		123-51762	Bigfoot 11-11-1	CI
482610	WELL	AP	07/27/2022		123-51763	Bigfoot 11-10-3	CI
482611	WELL	AP	07/27/2022		123-51764	Bigfoot 11-5-4	CI

**General Comment:**[This is a Construction and Stormwater Inspection in response to Form 42: Notice of construction- Document #403118657.](#)

### Location Construction

Location ID: 482275 CDP: \_\_\_\_\_

Comment: [Per Rule 406.c. a copy of the approved Form 2A was posted on location. Refer to the attached inspection photos.](#)

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

#### Form 2A COAs:

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

#### Wildlife BMPs:

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

#### On Site Inspection (305):

##### Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

##### Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

##### LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

##### Summary of Landowner Issues:

\_\_\_\_\_

##### Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

##### Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

Inspected Facilities				
Facility ID: <u>482606</u>	Type: <u>WELL</u>	API Number: <u>123-51759</u>	Status: <u>AP</u>	Insp. Status: <u>CI</u>
Facility ID: <u>482607</u>	Type: <u>WELL</u>	API Number: <u>123-51760</u>	Status: <u>AP</u>	Insp. Status: <u>CI</u>
Facility ID: <u>482608</u>	Type: <u>WELL</u>	API Number: <u>123-51761</u>	Status: <u>AP</u>	Insp. Status: <u>CI</u>
Facility ID: <u>482609</u>	Type: <u>WELL</u>	API Number: <u>123-51762</u>	Status: <u>AP</u>	Insp. Status: <u>CI</u>
Facility ID: <u>482610</u>	Type: <u>WELL</u>	API Number: <u>123-51763</u>	Status: <u>AP</u>	Insp. Status: <u>CI</u>
Facility ID: <u>482611</u>	Type: <u>WELL</u>	API Number: <u>123-51764</u>	Status: <u>AP</u>	Insp. Status: <u>CI</u>

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: DRY LAND

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND SEGREGATION PassComment Appears topsoil was salvaged and stored along the southern perimeter of the location in compliance with Rule 1002.b.

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS In ProcessComment Topsoil stockpile has been temporarily stabilized with straw mulch and corn stalks. Operator plans to seed into the topsoil stockpile as soon as possible.Per Rule 1002.c., all stockpiles shall be protected from degradation due to contamination, compaction and, to the extent practicable, from wind and water erosion during drilling and production operations. Per Rule 1002.c., BMPs to prevent weed establishment and to maintain soil microbial activity shall be implemented.

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION In ProcessComment Location is still under construction as cut and fill slopes were unconsolidated. However, there is a perimeter ditch and berm BMP around the entire perimeter of location. Operator representative on location indicated that the entire location would be seeded and straw crimped with mulch.Per Rule 1002.e.(1), Operator shall adequately construct and stabilize the entire well pad area, including cut and fill slopes, to control dust and minimize erosion, alteration of natural features, removal of surface materials, and degradation due to contamination.

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_

Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_

Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_

Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_

Recontoured \_\_\_\_\_

Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_

Recontoured \_\_\_\_\_

80% Revegetation \_\_\_\_\_

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

**Overall Interim Reclamation****Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_

Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: DRY LAND \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_

Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_

No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_

Contoured \_\_\_\_\_

Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_

Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_

Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_

Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_

Subsidence \_\_\_\_\_

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment:						
Corrective Action:						Date
Overall Final Reclamation		Well Release on Active Location <input type="checkbox"/>		Multi-Well Location <input type="checkbox"/>		

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Temporary BMPs have been installed (ditch and berm) around the entire perimeter during the construction phase of the location. More permanent BMPs are being constructed per Weld County requirements. A follow-up stormwater inspection will be conducted at a future date to ensure compliance with Rule 1002.f. standards. Refer to the COGCC Comments section for additional stormwater compliance information.

A vehicle tracking control device BMP (cattle guard) has been installed at the entrance of the location. The VTC appears to be in need of maintenance. There was no evidence of vehicle track out at the time of this inspection.

Refer to the COGCC Comments section for additional stormwater compliance information.

Corrective Action:

Date:

**Pits:** ☐ NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
Per Rule 1002.f., oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved pursuant to Rule 1004. Operators shall employ BMPs, as necessary to comply with this rule, at all oil and gas locations, including, but not limited to, well pads, soil stock piles, access roads, tank batteries, compressor stations, and pipeline rights of way. BMPs shall be selected based on site specific conditions, such as slope, vegetation cover, and proximity to water bodies, and may include maintaining in-place some or all of the BMPs installed during the construction phase of the facility. Where applicable based on site-specific conditions, operators shall implement BMPs in accordance with good engineering practices.	binschusc	08/11/2022

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
697504083	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5828027">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5828027</a>