

TEP
RWF 522-23
Location # 335132



location



location

TEP
RWF 522-23
Location # 335132



Signage illegible



Subsidence at tanks



TEP
RWF 522-23
Location # 335132



Subsidence at tanks



Subsidence at tanks (hard hat in subsidence)