

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/16/2022

Submitted Date:

08/17/2022

Document Number:

679604950

**FIELD INSPECTION FORM**

Loc ID 454188 Inspector Name: Santistevan, Brittani On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 69175  
Name of Operator: PDC ENERGY INC  
Address: 1775 SHERMAN STREET - STE 3000  
City: DENVER State: CO Zip: 80203

**Findings:**

- 6 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
438976	WELL	PR	01/01/2021	OW	123-40240	Greeley-Rothe Federal 32C-2-L	PR
454188	LOCATION	AC			-	Greeley-Rothe Federal 16-1 Pad	AC
454190	WELL	PR	06/01/2020	OW	123-46448	Greeley-Rothe 34N-2B-L	PR

**General Comment:**

Location			
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		Date: _____
<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	weeds inside wellhead fencing. See attached photos.		
Corrective Action:	Comply with Rule 606.		Date: <u>09/01/2022</u>
Type	OTHER		
Comment:	Stained soil at two wellheads. See attached photos.		
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and review self inspection processes per Rule 1002.(2).d.		Date: <u>09/01/2022</u>
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	6' chain link		
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Plunger Lift # 12			corrective date
Comment:			
Corrective Action:			Date:
Type: Bradenhead # 12			
Comment:			
Corrective Action:			Date:
<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:			Date:
<b>Flaring:</b>			
Type			

Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 438976 Type: WELL API Number: 123-40240 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

Facility ID: 454188 Type: LOCATION API Number: - Status: AC Insp. Status: AC

**Producing Well**

Comment:

Corrective Action:

Date:

Facility ID: 454190 Type: WELL API Number: 123-46448 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other		Other				

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<p><b>COGCC Inspection Report Summary</b>                      **Weather Conditions: sunny, dry ground.                      On Wednesday, August 17, 2022 at approximately 11:00, I, Inspector Brittani Santistevan, conducted an on-site inspection at GREELEY-ROTHER FEDERAL 16-1 PAD (PDC Energy), at location #: 454188 in WELD COUNTY Colorado.                      While there, I observed producing wellheads.                      During this inspection the following possible compliance issues were observed:                      1. It appears two wellheads have stained soil under master valve. Conduct maintenance on equipment, cleanup stained material and review self inspection processes per Rule 1002. (2).d. (Corrective Action Date: September 1, 2022) See attached photos #2, 4.                      2. Weeds inside wellhead fencing. Remove to comply with Rule 606. (Corrective Action Date: September 1, 2022) See attached photos #5, 6.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.                      This is a summary of inspection report.</p>	santistb	08/17/2022

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679604955	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5832986">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5832986</a>