

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/22/2022

Submitted Date:

08/22/2022

Document Number:

693507775

FIELD INSPECTION FORM

 Loc ID 319889 Inspector Name: Silver, Randy On-Site Inspection 2A Doc Num: _____
Operator Information:

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 Number of Comments

2 Number of Corrective Actions

-
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
,	303-825-4822	cogcc@kpk.com	All Inspections
Watzman, Ross	(303) 825-4822	rwatzman@kpk.com	all inspections.

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
201791	WELL	PR	06/01/2022	OW	001-07195	NORTH YORK 1	PR

General Comment:

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:		Date:	

Good Housekeeping:

Type	OTHER		
Comment:	Stained soil outside of berm around ECD		
Corrective Action:	Properly dispose of oily waste in accordance with 905.e.	Date:	09/22/2022
Type	OTHER		
Comment:	Out of service flowlines. It appears Sales meter has been removed from site and flow lines are not LOTO		
Corrective Action:	Comply with rule 1101 a	Date:	09/22/2022

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type: Gas Meter Run	# 1		corrective date
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			

Corrective Action:

Date:

Inspected FacilitiesFacility ID: 201791 Type: WELL API Number: 001-07195 Status: PR Insp. Status: PR**Producing Well**Comment: Corrective Action: Date: **BradenHead**Date of Last Brhd Test: 06/09/2022 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: End Surf Csg Pressure: 0Comment: Corrective Action: Date: **Workover**

Comment:

Corrective Action: Date: **COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary On Monday August 22, 2022 at approximately 11:12PM, I, Inspector Randy Silver, conducted an on-site inspection. Location: North York 1 Operator: KP Kauffman API#:001-07195 County: Adams While there, I observed a Producing well site with workover rig. During this inspection the following possible compliance issues were observed: Stained soil: Rule 905 e Corrective action date of 9-22-22 See photos 4,6 Out of service flowline: Rule 1101a Corrective action date of 9-22-22 See photo 5 Weather conditions: Clear I spoke with Walter he stated crew was performing a pump change. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	silverr	08/22/2022

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693507776	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5835824