

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
403132832

Date Received:  
08/11/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10724  
Name of Operator: NORTH SHORE EXPLORATION AND PRODUCTION LLC  
Address: 105 EDGEVIEW DR SUITE 400  
City: BROOMFIELD State: CO Zip: 80021

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>MARINA AYALA</u>	<u>3038925616</u>	<u>marina@northshoreenergyllc.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 702800524  
Inspection Date: 07/27/2022 FIR Submit Date: 08/04/2022 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: NORTH SHORE EXPLORATION AND PRODUCTION LLC Company Number: 10724  
Address: 105 EDGEVIEW DR SUITE 400  
City: BROOMFIELD State: CO Zip: 80021

LOCATION - Location ID: 313188

Location Name: MARTIN LIVESTOCK-610N93W Number: 17NWNW County: \_\_\_\_\_  
Qtrqtr: NWN Sec: 17 Twp: 10N Range: 93W Meridian: 6  
W  
Latitude: 40.831413 Longitude: -107.866292

FACILITY - API Number: 05-081-00 Facility ID: 313188

Facility Name: MARTIN LIVESTOCK-610N93W Number: 17NWNW  
Qtrqtr: NWN Sec: 17 Twp: 10N Range: 93W Meridian: 6  
W  
Latitude: 40.831413 Longitude: -107.866292

CORRECTIVE ACTIONS:

1  CA# 163740

Corrective Action: \_\_\_\_\_ Date: 11/15/2022

Comply with 1004 Rules.  
Conduct additional reclamation in accordance with COGCC 1000 series rules. Remove the riser to the south of the Location access road. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of pre-disturbance or reference area levels on the Location, access road and area of riser removal. Use a seed mixture requested by the surface owner, or a mixture prescribed by the local soil conservation district. Ensure erosion controls are implemented to stabilize the seeded soil, and continue to monitor and manage this site until Final Reclamation has passed. Revegetation activities shall be completed no later than 11/15/2022.

Response: CA COMPLETED

Date of Completion: 08/11/2022

Operator Comment: Per my conversation today with Anna O'Malley regarding the riser. The riser is not North Shore's, please see attached documentation.  
North Shore will apply more seed in October 2022.

COGCC Decision: **Not Approved**

COGCC Representative: COGCC can not accept "Corrective Action Completed" for future dates. Based on Operator comment, additional reclamation has not yet been performed on the Location.  
  
Documentation attached to this FIRR adequately demonstrates that the riser to the south of the Location access road is a water well which is not associated with oil and gas Operations. Corrective Action to remove the riser has been addressed and is no longer applicable.

**OPERATOR COMMENT AND SUBMITTAL**

Comment: Per my conversation today with Anna O'Malley regarding the riser. The riser is not North Shore's, please see attached documentation.  
North Shore will apply more seed in October 2022.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: MARINA AYALA

Signed: \_\_\_\_\_

Title: Engineering Technician

Date: 8/11/2022 10:00:49 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<b><u>Document Number</u></b>	<b><u>Description</u></b>
403132832	FIR RESOLUTION SUBMITTED
403132857	Map, water resource information

Total Attach: 2 Files