

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/24/2022

Submitted Date:

08/24/2022

Document Number:

696304386

**FIELD INSPECTION FORM**
 Loc ID 330245 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

7 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
Haverkamp, Curtis		curtis.haverkamp@state.co.us	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Burn, Diana		diana.burn@state.co.us	
Kraich, Adam		adam.kraich@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
250901	WELL	SI	05/01/2022	OW	123-18704	HSR-LOST CREEK/STATE 6-14	SI

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Wellhead not Visible; see photos		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	09/23/2022

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	Weeds around Wellsite; see photos		
Corrective Action:	Comply with Rule 606	Date:	09/08/2022

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Wellhead Gaurd off to the Side covered by weeds; see photos		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 0		
Comment:	Bradenhead STILL appears to be NOT plumbed to surface.		
Corrective Action:	Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2)	Date:	11/25/2022

<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	250901	Type:	WELL	API Number:	123-18704	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned      Reminder: _____									
Comment: <input type="text" value="SI"/>									
Corrective Action: <input type="text"/> Date: _____									

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Seeding		Seeding				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
Re-Inspection. Bradenhead STILL APPEARS to NOT be plumbed to surface.	petrie	08/24/2022

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403145888	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5838844">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5838844</a>
696304387	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5838842">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5838842</a>
696304388	Video of Wellhead	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5838843">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5838843</a>