

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403127419

Date Received:

08/04/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 39560

Name of Operator: TOP OPERATING COMPANY

Address: 3609 S WADSWORTH BLVD STE 340

City: LAKEWOOD State: CO Zip: 80235

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Paul Herring

Phone

7206631698

Email

paul.herring@topoperating.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 697503995

Inspection Date: 06/09/2022

FIR Submit Date: 06/13/2022

FIR Status: _____

Inspected Operator Information:

Company Name: TOP OPERATING COMPANY

Company Number: 39560

Address: 3609 S WADSWORTH BLVD STE 340

City: LAKEWOOD State: CO Zip: 80235

LOCATION - Location ID: 318928

Location Name: SERAFINI GAS UNIT-62N68W Number: 18NENE County: _____

Qtrqr: NENE Sec: 18 Twp: 2N Range: 68W Meridian: 6

Latitude: 40.142936 Longitude: -105.040198

FACILITY - API Number: 05-123-00 Facility ID: 318928

Facility Name: SERAFINI GAS UNIT-62N68W Number: 18NENE

Qtrqr: NENE Sec: 18 Twp: 2N Range: 68W Meridian: 6

Latitude: 40.142936 Longitude: -105.040198

CORRECTIVE ACTIONS:

1 ☒ CA# 162634

Corrective Action: Comply with Rule 1004 to collaborate with the tenant farmer by removing large cobble/rock from location.

Date: 05/26/2022

Comply with Rule 1004 to perform topsoil sampling to test for and compare topsoil quality to that of a nearby reference area.

The corrective date is the date the location was observed out of compliance.

Response: CA COMPLETED

Date of Completion: 08/04/2022

The soil sample analysis is attached. TOP is assessing the course of action which may involve removing soil

Operator Comment: from the location and replacing it with top soil.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. COGCC staff, Chris Binschus, emailed the Operator on 8/31/2022 indicating that a further discussion is required to better understand the soil results. Staff asked the Operator to reach out again to discuss in further detail.

OPERATOR COMMENT AND SUBMITTAL

Comment: Attached is the soil report for the Serafini facility.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Paul Herring

Signed: _____

Title: Landman

Date: 8/4/2022 4:47:35 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403127419	FIR RESOLUTION SUBMITTED
403127422	Soil Sample Analysis

Total Attach: 2 Files