

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/30/2022

Submitted Date:

09/01/2022

Document Number:

696204026**FIELD INSPECTION FORM**Loc ID 335190 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10433Name of Operator: LARAMIE ENERGY LLCAddress: 1700 LINCOLN ST STE 3950City: DENVER State: CO Zip: 80203**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Laramie		cogccnotifications@laramie-energy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
335190	LOCATION	AC			-	CC 0620-01 Pad	RI

General Comment:

On 8/30/2022, Reclamation Specialist Trujillo conducted an inspection on Laramie Energy LLC's CC 0620-01 Pad Location in Garfield County, Colorado.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	<p>It was observed in this inspection that tank the equipment that previously existed north of the wells on the Location has been removed; piper riser associated with the tank remains at the surface and OOSLAT, and bright protective mesh fence placed around.</p> <p>Unclear as to the use of the riser equipment for production activities on the Location; unused equipment requires removal pursuant to 606 requirements.</p>		
Corrective Action:	Submit within a FIRR, documentation detailing the current and/or future use of the riser equipment remaining on the Location.		Date: 09/08/2022

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Gravel and compaction BMPs to stabilize the location and minimize tracking/sediment transport shows signs of degradation (becomeing sparse) when compared to previous inspection photos. Ensure BMPs remain in proper functioning condition.

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	414410	1630733	

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696204027	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5846410