

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/29/2022

Submitted Date:

08/30/2022

Document Number:

700704535**FIELD INSPECTION FORM**Loc ID 334960 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

**General Comment:****COGCC Inspection Report Summary**

On Monday 8/29/2022 at approximately 1100, I, Inspector Scott Ramsey, conducted a routine inspection at Caerus C28, at Location # 334960 in Garfield county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area. Operator (Caerus) has provided documentation of their Best Management Practices for Sediment Tracking Controls.

During this inspection the following compliance issues were observed:

1. Access road is impassable.

Refer to photograph of observed compliance issue.

A follow up on this site inspection may be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

**Location****Lease Road:**

Type	Access		
comment:	<a href="#">See stormwater</a>		
Corrective ActionL		Date:	

Overall Good: ☐**Emergency Contact Number:**

Comment:		Date:	
Corrective Action:			

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Other	Fail			

Comment: 1. Access road is impassable.Corrective Action: Repair and maintain lease road to comply with rule 204.Date: 10/21/2022**Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403151329	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5843398">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5843398</a>
700704545	Photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5843390">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5843390</a>