

Tinker 02-09 1

Document number 702500347

Date Completed 9/2/2022

Erosion channels repaired



Wattle reset and dug out.



Burrow in berm repaired.

