

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/25/2022

Submitted Date:

09/13/2022

Document Number:

699700329

## FIELD INSPECTION FORM

 Loc ID 324068 Inspector Name: Heil, John On-Site Inspection  2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: 1058 COUNTY ROAD 215City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**2 Number of Comments0 Number of Corrective Actions Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Gardner, Mike		mgardner@terraep.com	
Fischer, Alex		alex.fischer@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
89068	WELL	PR	01/06/2000	GW	045-07398	AMERICAN SODA LLC GM 33-34	EI
482435	TANK BATTERY	AC	06/27/2022		-	TEP's GR 32-34-696 production facil 482435	EI
482475	SPILL OR RELEASE	AC			-	SPILL/RELEASE POINT	EI

**General Comment:**

On July 25, 2022, COGCC Environmental Staff (John Heil) conducted an environmental field inspection of TEP ROCKY MOUNTAIN LLC (TEP operator #96850) GR 32-34-696 Production Facility Location ID 324068 and Spill/Release ID 482475.

**Inspected Facilities**

Facility ID: 89068 Type: WELL API Number: 045-07398 Status: PR Insp. Status: EI

Facility ID: 482435 Type: TANK API Number: - Status: AC Insp. Status: EI

Facility ID: 482475 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: See Spill/Release ID 482475 for more information. 7/25/2022 COGCC staff conducted a visual inspection of the spill/release area and observed a fenced excavation measuring approximately 20'x10'x10' (LxWxH). See Photo Log for details.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Reportable:  YES                      GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699700330	20220725 Photo Log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5858316">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5858316</a>