

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/21/2022

Submitted Date:

09/21/2022

Document Number:

702500461**FIELD INSPECTION FORM**Loc ID 325099 Inspector Name: Klink, Alex On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10766Name of Operator: ARKOMA OPERATIONS LLCAddress: 2121 S COLUMBIA AVE SUITE 101City: TULSA State: OK Zip: 74114**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:11 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Price, Andrew	918-260-8324	aprice@arkomaops.com	All SW field inspections
, General		SJBcompliance@arkomaops.com	ALL SW field inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
213995	WELL	PR	12/15/1964	GW	067-05279	JACQUES 2-X	PR

General Comment:

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

LocationOverall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

OTHER

Comment: Impacted material at produced water tank (IMG 03).

Corrective Action: Remove impacted material and dispose of in approved manner per rule 906 and 1002.f.

Date: 10/06/2022

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type

TANK BATTERY

Comment: Produced water tank enclosed by wire fencing.

Corrective Action:

Date:

Equipment:

corrective date

Type: Flow Line

6

Comment: 2 2" lines from wellhead to separator, 2 2" lines at wellhead, 2" line from separator to produced water, 2" line from separator to gas meter run.

Corrective Action:

Date:

Type: Gas Meter Run

1

Comment: Gas meter calibration is within the last year.

Corrective Action:

Date:

Type: Bradenhead

1

Comment: Bradenhead is accessible.

Corrective Action:

Date:

Type: Ancillary equipment

1

Comment: Telemetry

Corrective Action:

Date:

Type: Horizontal Heated Separator

1

Comment:

Corrective Action:

Date:

Type: Bird Protectors

1

Comment: Separator vent stack is screened properly.

Corrective Action:

Date:

Type: Plunger Lift

1

Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLs	PBV STEEL		37.072470,-107.699909
Comment:	Partially buried produced water tank with steel mesh top.				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	90 bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities				
Facility ID: 213995	Type: WELL	API Number: 067-05279	Status: PR	Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:				Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Pass			
Check Dams	Pass					
		Compaction	Pass			
Berms	Pass					
Rip Rap	Pass					
Culverts	Pass					
Ditches	Pass					
Compaction	Pass					
Gravel	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702500462	Photo doc	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5866395