


**COLORADO OIL & GAS CONSERVATION COMMISSION**  
**FIELD INSPECTION REPORT**



|   |                         |   |  |
|---|-------------------------|---|--|
| <input checked="" type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION<br><input type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION |                         | 1120 Lincoln Street, Suite 801<br>Denver, CO 80203<br>(303)894-2100 |  |
| API No. 05- <i>075 - 60032</i>  |                         | LEASE NAME: <i>Mt Hope W-38</i>                                     |  |
| LOCATION: <i>SUNE 25-9N-54W</i>   |                         | OPERATOR: <i>Minahan</i>  |  |
| DATE: <i>2 April 98</i>   |                         | INSPECTOR: <i>Ed Binkley</i>  |  |
| Insp. Type: <i>ID</i>   | Insp. Status: <i>TA</i> | PA: Y    N  | Pass/Fail: P <input checked="" type="radio"/> F    Viol.: <input checked="" type="radio"/> Y    N    NOV: Y    N |

| INSPECTION ITEM  | COMMENTS  | INPUT |
|--|---|-------|
| <b>Well ID Signs</b><br>(Rule 210, 604.c(4))                   | ✓  |       |
| <b>Pits (Reserve/Production)</b><br>(Rule 902, 903, 904, 905)  |   |       |
| <b>Fences</b><br>(Rule 603.b.7, 604.C.(3), 1002.A)             |   |       |
| <b>Tank Battery Equipment</b><br>(Rule 603.b.3, 604)           |   |       |
| <b>Fire Walls/Berms/Dikes</b><br>(Rule 603.b.12, 604)          |   |       |
| <b>General Housekeeping</b><br>(Rule 603)                      | OK  |       |
| <b>Spills (Oil/Water)</b><br>(Rule 907)                        |   |       |
| <b>Bradenhead</b><br>(Rule 207.b)                              | <i>shut in casing top -</i>   |       |
| <b>Drilling Well/Workover</b><br>(Rule 317)                    |   |       |
| <b>Surface Rehabilitation</b><br>(Rule 1002, 1003, 1004, 1103) |   |       |
| <b>Miscellaneous</b>   | <i>Bottom hole plug set.</i>  |       |

**CORRECTIVE ACTION REQUIRED:**

Date Corrective Action Required By:

Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.