



00241560

RECEIVED

DEC - 9 1966

COLO. OIL & GAS CONS. COMM.

**OIL AND GAS CONSERVATION COMMISSION
OF THE STATE OF COLORADO**

SUNDRY NOTICES AND REPORTS ON WELLS

INSTRUCTIONS

Notice must be given to the Director, and approval obtained in advance of the time when the owner or operator expects to recompleate or abandon a well or to change plans. Within thirty (30) days after recompleation, change of plans, or remedial work, a detailed report of the work done and the results obtained shall be submitted on this form in duplicate for wells on Patented and Federal lands, and in triplicate for wells on State lands. In work that affects only rods, pumps or tubing or other routine work such as, but not limited to, cleaning out to previous total depth, no report is necessary.

Notice of Intention to Recomplete

☐

Report of Remedial Work

☐

Notice of Intention to Change Plans

☐

Report of Recompleation

☒

Notice of Intention to Abandon Well

☐

Other

☐

(Check appropriate space)

LEASE NAME Kinzie WELL NO. 1

FIELD Tomahawk WILDCAT - COUNTY Logan

LOCATION NE NE Section 10 Township 9N Range 55W Meridian 6

660 feet from N Section Line and 660 feet from E Section Line

N or S E or W

(DETAILS OF WORK)

1. Pulled rods and tubing
2. Squeezed perforations @ 5587' - 89' KB w/ 86 sx. type "G" cement and 2/10% HR-4.
3. Drilled out cement plug from 5522' to 5589' KB. Cleaned out to TD 5598' KB.
4. Tested squeeze. No entry after swabbing hole dry.
5. Perforated J-3 sand from 5580' - 83' KB w/4 jets/ft. under 250 gal. 10% NE acid.
6. Sandfraced 5580' - 83' KB w/5000 gal. lease crude, 5000# 20-40 sand, 300# adomite.
7. Cleaned up well and ran rods, tubing, and bottom hole pump.
8. Tested: 1-24-66, 2.64 BOPD, 100 BWPD, no gas, frac oil not recovered.

DVR	
WRS	
HMM	
JAM	
FJP	<input checked="" type="checkbox"/>
JJD	<input checked="" type="checkbox"/>
FILE	

I/We hereby swear (or affirm) that the statements herein made are a full and correct report.

APPROVED:

DEC 13 1966

Date

Director

Company Depco Inc.Date 12-8-66

825 Petroleum Club Bldg.

Address Denver, Colo. 80202Phone No. 292-0980

By

(Signature)

Title Dist. Prod. Supt.