

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/27/2022

Submitted Date:

09/29/2022

Document Number:

689501413

## FIELD INSPECTION FORM

 Loc ID 318065 Inspector Name: Brown, Kari On-Site Inspection  2A Doc Num: \_\_\_\_\_
**Operator Information:**
 OGCC Operator Number: 47120  
 Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP  
 Address: P O BOX 173779  
 City: DENVER State: CO Zip: 80217-
**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 6 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		COGCCInspections@Oxy.com	All Inspections
Hamilton, Greg		Gregory_Hamilton@oxy.com	Oxy Environmental

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
482753	SPILL OR RELEASE	CL	08/12/2022		-	Varra 10-2 Wellhead	EI

**General Comment:**

This is an environmental inspection of Spill ID 482753 (CL)/Remediation Project No 24096. Any corrective actions from previous inspections that have not been addressed are still applicable.

Photo attached to document site conditions.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>				
Type	OTHER			
Comment:	Chain link fence present around the excavation area but fencing is not fully closed (see attached photo).			
Corrective Action:	Secure access to excavation in compliance with Rule 913.b.(5).B.i and COGCC Guidance 913.b.(5)B i-v			Date: 10/06/2022

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 482753 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: Excavation was open at the time of inspection. No impacts were visible in situ. Groundwater was observed in the open excavation and was covered with orange now fencing.

Corrective Action:  Date: \_\_\_\_\_

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Waste Management:**

Type	Management	Condition	GPS (Lat) (Long)
Comment	<span style="border: 1px solid black; padding: 2px;">Soil was stored on location with earthen berms. Earthen berms did not completely surround the soils pile.</span>		
Corrective Action	<span style="border: 1px solid black; padding: 2px;">Manage soils in compliance with Rule 913.b.iv and COGCC Guidance 913.b.(5)B i-v.</span>		Date: <span style="border: 1px solid black; padding: 2px;">10/13/2022</span>

**Spill/Remediation:**

Comment:

Corrective Action:  Date: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment:

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689501414	Spill excavation	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5874121">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5874121</a>
689501415	Site fencing	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5874122">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5874122</a>
689501416	Soils pile	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5874123">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5874123</a>