

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/04/2022

Submitted Date:

10/04/2022

Document Number:

707900013

FIELD INSPECTION FORMLoc ID 318579 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Watzman, Ross	(303) 825-4822	rwatzman@kpk.com	all inspections.
,	303-825-4822	cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241643	WELL	PR	01/01/2020	OW	123-09432	UPRR 43 PAN AM B 12	PR

General Comment:

LocationOverall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:	Sign not legible		
Corrective Action:	Install sign to comply with Rule 605.g.	Date:	11/04/2022

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 241643 Type: WELL API Number: 123-09432 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 10/11/2021 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: -- Fluid Type: End Surf Csg Pressure: --

Comment:

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>Inspection due to form 42 MIRU notice. At time of inspection there was no crew onsite. COGCC Inspection Report Summary</p> <p>On Tuesday October 4, 2022 at approximately 10:00AM, I, Inspector Randy Silver, conducted an on-site inspection.</p> <p>Location: UPRR 43 Pan AM B#12</p> <p>Operator: KP Kauffman</p> <p>API#: 123-09432</p> <p>County: Weld</p> <p>While there, I observed a producing well site</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Sign: Rule 605 g Corrective action date of 11-4-22 see photo 2</p> <p>Weather conditions: wet and cloudy</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	silverr	10/04/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707900014	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5877215