

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/06/2022

Submitted Date:

10/06/2022

Document Number:

707900033**FIELD INSPECTION FORM**Loc ID 318743 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1700 LINCOLN ST STE 4550City: DENVER State: CO Zip: 80203**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Watzman, Ross	(303) 825-4822	rwatzman@kpk.com	all inspections.
Pesicka, Conor		conor.pesicka@state.co.us	
,	303-825-4822	cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
242082	WELL	PR	07/01/2022	OW	123-09873	UPRR 43-PAN AM I 32	SI

General Comment:

LocationOverall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	Operator installed sticker on old faded sign. Does not comply with rule 605g or 605d		
Corrective Action:	Operators will ensure that signs are well maintained and legible, and will replace damaged or vandalized signs within 30 days of discovery that the sign is no longer legible or is damaged.	Date:	08/08/2022

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 242082 Type: WELL API Number: 123-09873 Status: PR Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: At time of inspection flow line valves are in the closed position.

Corrective Action: Date:

BradenHead

Date of Last Brhd Test: 03/24/2022 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action: Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Thursday October 6 2022 at approximately 11:32AM, I, Inspector Randy Silver, Conducted an on-sitere- inspection Per doc#693507511.. Location: UPRR 43 Pan AM I32 Operator: KP Kauffman API#:123-09873 County: Weld While there, I observed shut in well site. During this inspection the following possible compliance issues were observed: Sign: Rule 605 g Corrective action date of 8-7-22 See photo 2 At time of inspection it appears KPK cut weeds on road and location. Operator installed sticker for faded sign corrective action. This does not comply with the rule in section 605. Weather conditions: Dry A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report</p>	silverrr	10/06/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707900034	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5880307