

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/28/2022

Submitted Date:

10/04/2022

Document Number:

702800757

FIELD INSPECTION FORM

Loc ID 399184 Inspector Name: O'Malley, Anna On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 51922
Name of Operator: LYSTER OIL COMPANY INC
Address: 701 COUNTY ROAD 105
City: CRAIG State: CO Zip: 81625

Findings:

- 6 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Lyster, Sue	(970) 824-6854	sue.lyster@cfbmic.com	All Inspections
Stewart, Amanda	(970) 326-8820	amanda.lysteroil@gmail.com	All Inspections
, Lyster	(970) 824-6854	lysteroil@yahoo.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
232498	WELL	PA	09/27/1988	DA	107-05066	MCDERMOTT-FEDERAL (GOV) 1-24	RI
399184	LOCATION	CL			-	MCDERMOTT-FEDERAL (GOV)-66N86W 24SESE	RI

General Comment:

On 09/28/2022, Reclamation Specialist O'Malley conducted a follow up to inspection #702800526 at Lyster Oil Company Inc's McDermott-Federal (GOV)-66N86W /24SESE Location #399184 in Routt County, Colorado.

The following compliance issues were observed during this inspection:
- Equipment/debris remains on Location

Refer to the "Reclamation" and "COGCC Comments" sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Inspected Facilities

Facility ID: 232498 Type: WELL API Number: 107-05066 Status: PA Insp. Status: RI

Facility ID: 399184 Type: LOCATION API Number: - Status: CL Insp. Status: RI

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____

Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed **Fail** _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

Comment: [Refer to the "COGCC Comments" section of this inspection report for "Final Reclamation Comments".](#)

Corrective Action: **Comply with 1004 Rules; remove all buried pipes and debris from the Location. Implement long term stabilization of areas disturbed by buried pipe removal.**

Date **09/29/2022**

Overall Final Reclamation

In Process

Well Release on Active Location Multi-Well Location **COGCC Comments**

Comment	User	Date
<p>Final Reclamation Comments</p> <p>Previous inspection #702800526 observed multiple buried pipes throughout the fill slope of the Location. Pipes run parallel to the slope/come out of the fill and also run perpendicular to the slope. Loose pipe and cable debris is also present on the ground surface of the pad. Inspector required Operator to remove all buried pipes and debris from the Location. Implement long term stabilization of areas disturbed by buried pipe removal by 9/29/2022.</p> <p>Operator submitted FIRR #403142838 indicating cleaned up location of all pipes.</p> <p>It was observed in this inspection the one pipe remains buried in the fill slope which was indicated in previous inspection photos. A cable is also present nearby. Pipe debris was also remaining on the soil surface. Inspector piled debris at well marker for removal. See attached photos for remaining buried pipe, cable and debris approximate location and coordinates. Original corrective action and date remain applicable.</p>	omalleya	10/04/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403187345	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5877822
702800758	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5877821