

Location			
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Adequate		Date: _____
Corrective Action:			
Good Housekeeping:			
Type	OTHER		
Comment:	Stained soil in multiple spots next to the well needs to be removed. See attached photos.		
Corrective Action:	"Properly dispose of oily waste in accordance with 905.e."		Date: <u>10/20/2022</u>
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type: Plunger Lift	# 1		corrective date
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:			Date:
Type: Other	#		
Comment:	Mechanical conditions in multiple spots needs repaired or replaced. See attached photos.		
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.		Date: <u>10/20/2022</u>
Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:
Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected FacilitiesFacility ID: 455186 Type: WELL API Number: 123-46919 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 05/04/2022 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Monday 10/10/22 at approximately 0936hrs, I, Inspector Adam Burns, Conducted an on-site inspection at North Platte K-O-28HNC of Civitas, at API # 05-123-46919 in Weld County, Colorado. During this inspection the following possible compliance issues were observed: Stained soil in multiple spots next to the well needs to be removed. "Properly dispose of oily waste in accordance with 905.e." With a corrective action date of 10/20/22. Mechanical conditions in multiple spots needs repaired or replaced. Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e. With a corrective action date of 10/20/22. See attached photos. Submit pictures on FIRR. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	burnsa	10/11/2022

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699106139	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5883236