

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/06/2022

Submitted Date:

10/06/2022

Document Number:

707900038

FIELD INSPECTION FORMLoc ID 318748 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,	303-825-4822	cogcc@kpk.com	All Inspections
Watzman, Ross	(303) 825-4822	rwatzman@kpk.com	all inspections.

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
242098	WELL	PR	07/01/2022	OW	123-09889	UPRR 43 PAN AM I 31	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

OTHER

Comment:

Stained soil around well head.

Corrective Action:

Properly dispose of oily waste in accordance with 905.e.

Date: 08/07/2022

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No

NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected FacilitiesFacility ID: 242098 Type: WELL API Number: 123-09889 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 08/24/2022 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

COGCC Comments

Comment

User

Date

COGCC Inspection Report Summary
 On Thursday June 7 2022 at approximately 12:00PM, I, Inspector Randy Silver,
 Conducted an on-site re-inspection Per doc#693507513.
 Location: UPRR 43 Pan AM I #31
 Operator: KP Kauffman
 API#:123-09889
 County: Weld
 While there, I observed producing in well site.
 During this inspection the following possible compliance issues were observed:
 Stained soil: Rule 905 e Corrective action date of 8-7-22 See photo 2
 At time of inspection it did not appear stained soil around well head had been addressed.
 Weather conditions: Dry and cloudy.
 A follow up on this site inspection needs to be conducted to ensure the
 compliance issues have been corrected to comply with COGCC rules.
 This is a summary of inspection report

silverr

10/06/2022

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403190234	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5880316
707900039	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5880309