

# Parker 11-33 (05-123-20832): Off-Location Flowline Abandonment

40.188367, -104.902724

NWNW Sec. 33 T3N, R67W, 6th PM

Weld County, Colorado

Crestone Peak Resources (10633)

Flowline Unique OperFeatID	Line Type	Start Location	Start Location Latitude	Start Location Longitude	End Location	End Location Latitude (Cut Point)	End Location Longitude (Cut Point)	Approx. Length to Abandon (ft)
Parker 11-33: 12320832_FL	Multiphase	Wellhead	40.188367	-104.902724	Separator	40.186963	-104.899801	2160



## Site Investigation Points

✗ Visual Inspection and Soil Sample

# Parker 12-33 (05-123-19342): Off-Location Flowline Abandonment

40.184170, -104.902706

SWNW Sec. 33 T3N, R67W, 6th PM

Weld County, Colorado

Crestone Peak Resources (10633)

Flowline Unique OperFeatID	Line Type	Start Location	Start Location Latitude	Start Location Longitude	End Location	End Location Latitude (Cut Point)	End Location Longitude (Cut Point)	Approx. Length to Abandon (ft)
Parker 12-33: 12319342_FL	Multiphase	Wellhead	40.184170	-104.902706	Separator	40.186924	-104.899847	2045



## Site Investigation Points

✗ Visual Inspection and Soil Sample

# Parker 22-33 (05-123-20834): Off-Location Flowline Abandonment

40.184110, -104.897650 (Parker 22-33)

40.184000, -104.897800 (Parker 2-4-33)

SENW Sec. 33 T3N, R67W, 6th PM

Weld County, Colorado

Crestone Peak Resources (10633)

Flowline Unique OperFeatID	Line Type	Start Location	Start Location Latitude	Start Location Longitude	End Location	End Location Latitude (Cut Point)	End Location Longitude (Cut Point)	Approx. Length to Abandon (ft)
Parker 22-33: 12320834_FL	Multiphase	Wellhead	40.184110	-104.897650	Separator	40.18691	-104.899796	1295



## Site Investigation Points

✗ Visual Inspection and Soil Sample