

# State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
403200476

Date Received:  
10/18/2022

## FIR RESOLUTION FORM

### Overall Status:

#### CA Summary:

1 of 2 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: <u>96850</u>	Contact Name and Telephone:
Name of Operator: <u>TEP ROCKY MOUNTAIN LLC</u>	Name: _____
Address: <u>1058 COUNTY ROAD 215</u>	Phone: ( ) _____ Fax: ( ) _____
City: <u>PARACHUTE</u> State: <u>CO</u> Zip: <u>81635</u>	Email: _____

#### Additional Operator Contact:

Contact Name	Phone	Email
<u>.Inspections</u>		<u>COGCCInspectionReports@terraep.com</u>

### COGCC INSPECTION SUMMARY:

FIR Document Number: 696203985  
 Inspection Date: 08/15/2022 FIR Submit Date: 08/19/2022 FIR Status: \_\_\_\_\_

#### Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC Company Number: 96850  
 Address: 1058 COUNTY ROAD 215  
 City: PARACHUTE State: CO Zip: 81635

#### LOCATION - Location ID: 334776

Location Name: FEDERAL-67S95W Number: 12SESW County: \_\_\_\_\_  
 Qtrqr: SESW Sec: 12 Twp: 7S Range: 95W Meridian: 6  
 Latitude: 39.446006 Longitude: -107.947547

#### FACILITY - API Number: 05-045-00 Facility ID: 334776

Facility Name: FEDERAL-67S95W Number: 12SESW  
 Qtrqr: SESW Sec: 12 Twp: 7S Range: 95W Meridian: 6  
 Latitude: 39.446006 Longitude: -107.947547

### CORRECTIVE ACTIONS:

**2** CA# 163985

Corrective Action: Comply with 1002.f and implement stabilization and tracking BMPs; regrading efforts alone will be insufficient. Date: 08/26/2022

Response: CA COMPLETED Date of Completion: 08/22/2022

Operator Comment: Location was bladed and 8 loads of gravel were delivered and spread across problem spots on the pad. Corrective action #163985 is complete.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment: Location was bladed and 8 loads of gravel were delivered and spread across soft spots on the pad. Corrective action #163985 is complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Gardner

Signed: \_\_\_\_\_

Title: TEP Environmental Lead

Date: 10/18/2022 10:54:44 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

**Document Number**      **Description**

<b><u>Document Number</u></b>	<b><u>Description</u></b>

Total Attach: 0 Files