

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/19/2022

Submitted Date:

10/19/2022

Document Number:

707900074**FIELD INSPECTION FORM**Loc ID 322261 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 44390Name of Operator: JAVERNICK OILAddress: 3040 E MAINCity: CANON CITY State: CO Zip: 81212**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**11 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Beardslee, Tom		tom.beardslee@state.co.us	
Javernick, James	719-275-3040/719-671-3787	javernick1@gmail.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210081	WELL	PR	02/01/2022	OW	043-40017	MARJO M2	PR

General Comment:

Location

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	It appears a new line from the Draper #2 has been run to the crude oil tank. no sign has been installed		
Corrective Action:	Comply with rule 605 e	Date:	11/19/2022
Type	TANK LABELS/PLACARDS		
Comment:	Sign or label not posted or information inaccurate on tanks or containers or sign/label too small to read at distance or installed in place where not visible.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	11/19/2022

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Stained soil around crude oil load lines and PU		
Corrective Action:	Properly dispose of oily waste in accordance with 905.e.	Date:	11/19/2022
Type	OTHER		
Comment:	Mechanical issue crude oil load lines and PU		
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.	Date:	11/19/2022

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Electric panel		
Corrective Action:		Date:	
Type: Prime Mover	# 1		

Comment: Electric motor			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	300 BBLs	STEEL AST		38.298115,-105.103184	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Wells Served By Facilities Above

API Number
043-06149
043-40016
043-40017
043-40018

AirsID

API Number	AirsID
------------	--------

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 210081 Type: WELL API Number: 043-40017 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: _____ Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: _____ Fluid Type: _____

End Surf Csg Pressure: _____

Comment: Submit reports

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Tuesday October 19, 2022 at approximately 3:44PM, I, Inspector Randy Silver, conducted an on-site inspection.</p> <p>Location: Marjo #M2</p> <p>Operator: Javernick Oil</p> <p>API#: 043-40017</p> <p>County: Freemont</p> <p>While there, I observed a producing well site and facility.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Tank labels: Rule 605h Corrective action date of 11-19-22 see photo 3</p> <p>Mechanical issue: Rule 608e Corrective action date of 11-19-22 See photos 4,5</p> <p>Stained soil: Rule 905e Corrective action date of 11-19-22 See photos 4,5</p> <p>Battery Sign: Rule 605 e Corrective action date of 11-19-22</p> <p>Weather conditions: Clear</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	silverr	10/19/2022

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707900075	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5891346