

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403200196

Date Received:

10/18/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

TEP

COGCCInspectionReports@terraep.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 699805029

Inspection Date: 10/07/2022

FIR Submit Date: 10/10/2022

FIR Status: _____

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 324247

Location Name: LAST DANCE-66S92W Number: 34SESE County: _____

Qtrqr: SESE Sec: 34 Twp: 6S Range: 92W Meridian: 6

Latitude: 39.478081 Longitude: -107.643722

FACILITY - API Number: 05-045- -00 Facility ID: 324247

Facility Name: LAST DANCE-66S92W Number: 34SESE

Qtrqr: SESE Sec: 34 Twp: 6S Range: 92W Meridian: 6

Latitude: 39.478081 Longitude: -107.643722

CORRECTIVE ACTIONS:

1 ☒ CA# 165158

Corrective Action: The storage of equipment not necessary for use on location is prohibited.

Date: 11/10/2022

Response: CA COMPLETED

Date of Completion: 10/11/2022

Operator Comment: Per the TEP production supervisor for this location, the equipment noted in the inspection report is fully functional and is used / connected when needed for site operations. The equipment noted in the report is both necessary and used as needed to support site operations. The corrective action has been addressed.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2 ☒ CA# 165159

Corrective Action: Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations

Date: 10/25/2022

Response: CA COMPLETED

Date of Completion: 10/11/2022

Operator Comment: Per the production supervisor for this location, the site is stable and BMPs are functioning as designed. The site was simply wet and muddy at the time that the COGCC inspector drove upon the location. As needed, the location is periodically bladed to remove any ruts that were created by traffic accessing the location during / soon after a storm event.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Both corrective actions have been addressed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Gardner

Signed:

Title: TEP Environmental Lead

Date: 10/18/2022 9:23:04 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403200196	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files