

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403205009

Date Received:
10/21/2022

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Victoria Dizghinjili

Phone

303-825-4822

Email

vdizghinjili@kpk.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 688313264

Inspection Date: 10/10/2022

FIR Submit Date: 10/12/2022

FIR Status: _____

Inspected Operator Information:

Company Name: KP KAUFFMAN COMPANY INC

Company Number: 46290

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

LOCATION - Location ID: 320756

Location Name: STATE-64S62W Number: 14SWNE County: ARAPAHOE

Qtrqr: SWNE Sec: 14 Twp: 4S Range: 62W Meridian: 6

Latitude: 39.704261 Longitude: -104.291482

FACILITY - API Number: 05-005-

-00

Facility ID: 204815

Facility Name: STATE

Number: 14-32

Qtrqr: SWNE Sec: 14 Twp: 4S Range: 62W Meridian: 6

Latitude: 39.704261 Longitude: -104.291482

CORRECTIVE ACTIONS:

1 CA# 165213

Corrective Action: Calibrate gas metering equipment annually to comply with rule 430.d.(1).

Date: 11/14/2022

Response: CA COMPLETED

Date of Completion: 10/21/2022

Operator
Comment:

KPK's production crew began fueling some equipment in execution of KPK's Gas Capture Plan. However, the minimal gas production during these operations was fully consumed by the equipment on location, no selling gas.

COGCC Decision:

COGCC Representative:			
2	CA# 165214		
Corrective Action:	Install or repair required BMPs per Rule 1002.f(2)C	Date: <u>10/21/2022</u>	
Response:	<u>CA COMPLETED</u>	Date of Completion: <u>10/21/2022</u>	
Operator Comment:	BMPs have been repaired. Please see attached pictures.		
COGCC Decision:			
COGCC Representative:			
3	CA# 165215		
Corrective Action:	Lack of pit liner or pit liner compromised (Rule 910). IMMEDIATE NOTIFICATION TO THE OPERATOR Reduce fluid level in pit, contact COGCC EPS staff for directives.	Date: <u>10/21/2022</u>	
Response:	<u>CA COMPLETED</u>	Date of Completion: <u>10/21/2022</u>	
Operator Comment:	Corrective action was completed. Please see attached pictures.		
COGCC Decision:			
COGCC Representative:			

OPERATOR COMMENT AND SUBMITTAL	
Comment:	
<p>I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.</p> <p>Print Name: <u>Victoria Dizghinjili</u> Signed: _____</p> <p>Title: <u>Engineering Tech</u> Date: <u>10/21/2022 1:19:10 PM</u></p>	

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403205131	CA completed PIC1
403205135	CA completed PIC2
403205136	CA completed PIC3

Total Attach: 3 Files