

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/25/2022

Submitted Date:

10/24/2022

Document Number:

702500652**FIELD INSPECTION FORM**Loc ID 325498 Inspector Name: Klink, Alex On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 25250Name of Operator: DUGAN PRODUCTION CORPAddress: P O BOX 420City: FARMINGTON State: NM Zip: 87499-**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 11 Number of Comments
- 2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Wheeler, Cody		Cody.Wheeler@duganproduction.com	SW Field inspections
Labowskie, Steve		steve.labowskie@state.co.us	
Feil, Tyra		tyrafeil@duganproduction.com	SW Field inspections
Alexander, John		johncalexander@duganproduction.com	SW Inspections
Smaka, Kevin		kevin.smaka@duganproduction.com	
Heslop, Jason		Jason.Heslop@duganproduction.com	SW Field inspections
Foutz, Marty		marty.foutz@duganproduction.com	All SW field inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214894	WELL	PR	02/28/2011	GW	067-06498	TIFFANY 1	PR

General Comment:

Inspector Alex Klink on site to conduct follow up inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	OTHER		
Comment:	CA regarding impacted material from previous inspection Doc# 702500365 has been satisfactorily completed.		
Corrective Action:		Date:	
Type	UNUSED EQUIPMENT		
Comment:	CA from previous inspection Doc# 702500365 has been satisfactorily completed.		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Flow Line	#		corrective date
Comment:	Open ended valve on out of use flow line near separator is not locked out (IMG 05). Open ended valve on out of use flow line near wellhead is not locked out (IMG 05).		
Corrective Action:	Apply Out of Service Locked and Tagged on unused flow line per rule 1101.a(3)		Date: 10/27/2022

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLS	OTHER		37.036016,-107.581546
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	CA from previous inspection Doc# 702500365 has been satisfactorily completed.			
Corrective Action:				Date:

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: 214894	Type: WELL	API Number: 067-06498	Status: PR	Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:				Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Comment: Access road has ruts ~6"-8" deep (IMG 03 and IMG 04) and is not satisfactorily maintained. CA date remains from previous inspection. Well location has been improved and is satisfactory (IMG 02).						Date: 10/20/2022
Corrective Action: Install or repair/modify required BMPs per Rule 1002.f.(2)C						
Pits: <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT						

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702500653	Photo doc	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5894948