

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
403200036

Date Received:  
10/18/2022

## FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 10722

Name of Operator: KTM OPERATING LLC

Address: 2851 JOHNSTON ST PMB 550

City: LAFAYETTE State: LA Zip: 70503

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Hecht, Jaime

832-531-1711

jaime.hecht@dynacloud.io

Boudreaux, Benjamin

Benjamin.Boudreaux@coag.gov

Lee, Kris

krislee@skybeam.com

Vincent, Kenny

(337) 654-9404

kvincent@reagan.com

### COGCC INSPECTION SUMMARY:

FIR Document Number: 688313127

Inspection Date: 09/14/2022

FIR Submit Date: 10/05/2022

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: KTM OPERATING LLC

Company Number: 10722

Address: 2851 JOHNSTON ST PMB 550

City: LAFAYETTE State: LA Zip: 70503

### LOCATION - Location ID: 430069

Location Name: Knoss Number: 6-21 County: LINCOLN

Qtrqtr: SENW Sec: 21 Twp: 12S Range: 56W Meridian: 6

Latitude: 38.992880 Longitude: -103.677310

### FACILITY - API Number: 05-073-00 Facility ID: 430071

Facility Name: Knoss Number: 6-21

Qtrqtr: SENW Sec: 21 Twp: 12S Range: 56W Meridian: 6

Latitude: 38.992880 Longitude: -103.677310

### CORRECTIVE ACTIONS:

1 ☒ CA# 165038

Corrective Action:

Date: 10/20/2022

"For localized stained soils or oily waste - ""Properly dispose of oily waste in accordance with 905.e.""  
Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.

Response: CA COMPLETED

Date of Completion: 10/14/2022

Operator Comment: The oily soil around well head has been removed and placed in a 5 gallon sealed bucket and marked. The soil is replaced with new clean soil.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Kristina Lee

Signed: \_\_\_\_\_

Title: Regulatory Consultant-KTM

Date: 10/18/2022 7:41:09 AM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403200036	FIR RESOLUTION SUBMITTED
403200045	Clean up photo

Total Attach: 2 Files