

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402987977

Date Received:  
03/17/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 4 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1700 LINCOLN ST STE 4550  
City: DENVER State: CO Zip: 80203

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Victoria Dizghinjili</u>	<u>303-825-4822</u>	<u>vdizghinjili@kpk.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 693506177  
Inspection Date: 01/05/2022 FIR Submit Date: 01/05/2022 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: KP KAUFFMAN COMPANY INC Company Number: 46290  
Address: 1675 BROADWAY, STE 2800  
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 318749

Location Name: UPRR 43 PAN AM I-61N68W Number: 13NWSW County: WELD  
Qtrqr: NWS Sec: 13 Twp: 1N Range: 68W Meridian: 6  
W  
Latitude: 40.049643 Longitude: -104.959640

FACILITY - API Number: 05-123-00 Facility ID: 242099

Facility Name: UPRR 43 PAN AM I Number: 30  
Qtrqr: NWS Sec: 13 Twp: 1N Range: 68W Meridian: 6  
W  
Latitude: 40.049643 Longitude: -104.959640

CORRECTIVE ACTIONS:

1  CA# 159032

Corrective Action: Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2) Date: 02/05/2022

Response: CA COMPLETED Date of Completion: 03/01/2022

Operator Comment: Bradenhead access was installed before inspection but wasn't visible. Please see attached picture.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Will reinspect

**3**  CA# 159034

Corrective Action: Comply with rule 606

Date: 02/05/2022

Response: CA COMPLETED

Date of Completion: 03/01/2022

Operator Comment: Unused wiring and unmarked riser have been removed.

COGCC Decision: **Not Approved**

COGCC Representative: Operator picture clearly shows electric wiring sticking out of the ground, (top left of cement base)

**4**  CA# 159035

Corrective Action: Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.

Date: 02/05/2022

Response: CA COMPLETED

Date of Completion: 03/01/2022

Operator Comment: Mechanical issues have been fixed. Please see attached picture.

COGCC Decision: Approved pending re-inspection

COGCC Representative: will reinspect

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Victoria Dizghinjili

Signed: \_\_\_\_\_

Title: Engineering Tech

Date: 3/17/2022 2:01:59 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402987977	FIR RESOLUTION SUBMITTED
402987984	Well head PIC1
402987985	Bradenhead access PIC2
402987987	Removed some unused equipment PIC3

Total Attach: 4 Files