

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/27/2022

Submitted Date:

10/28/2022

Document Number:

700704654**FIELD INSPECTION FORM**
 Loc ID 324112 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

6 Number of Comments

2 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
257412	WELL	PR	05/26/2000	GW	045-07560	CLOUGH RMV 239-29	PR

**General Comment:****COGCC Inspection Report Summary**

On Thursday 10/27/2022 at approximately 1100, I, Inspector Scott Ramsey, conducted a follow up inspection at TEP RMV 239-29, at Location # 324112 in Garfield county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for a tracking pad.

C/A from previous inspection document # 700702544 has not been completed.

During this inspection the following compliance issues were observed:

1. Access to location shows signs of lack of stabilization and tracking onto county road.

2. Well sign is lacking API #

Refer to photograph of observed compliance issue.

A follow up on this site inspection may be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

**Location****Lease Road:**

Type	Access		
comment:	See stormwater		
Corrective Action		Date:	

Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:	Well sign is lacking API #		
Corrective Action:	Provide proper labeling	Date:	05/07/2021

**Emergency Contact Number:**

Comment:	911		
Corrective Action:		Date:	

**Good Housekeeping:**

Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

**Equipment:**

Type: Plunger Lift	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	257412	Type:	WELL	API Number:	045-07560	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:				Date:					

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction	Fail			

Comment: 1. Access to location shows signs of lack of stabilization and tracking onto county road.

Corrective Action: Install or repair required BMPs. Maintain vehicle tracking BMPs on the oil and gas location. Additionally, if material is tracked onto county or public roads, contact the appropriate authority.

Date: 11/04/2022

Pits: ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700704659	Photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5900317">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5900317</a>