

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403213258

Date Received:

10/31/2022

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 6 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10651

Name of Operator: VERDAD RESOURCES LLC

Address: 1125 17TH STREET SUITE 550

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Michael Cugnetti

Phone

720-845-6901

Email

mcugnetti@verdadresources.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696105527

Inspection Date: 10/11/2022

FIR Submit Date: 10/19/2022

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: VERDAD RESOURCES LLC

Company Number: 10651

Address: 1125 17TH STREET SUITE 550

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 466345

Location Name: Boydston Number: 3535 County: \_\_\_\_\_

Qtrqr: NWN Sec: 35 Twp: 9N Range: 60W Meridian: 6  
W

Latitude: 40.712886 Longitude: -104.067521

FACILITY - API Number: 05-123- -00 Facility ID: 466345

Facility Name: Boydston Number: 3535

Qtrqr: NWN Sec: 35 Twp: 9N Range: 60W Meridian: 6  
W

Latitude: 40.712886 Longitude: -104.067521

CORRECTIVE ACTIONS:

1 CA# 165505

Corrective Action: Comply with Rule 1002.f.(2).d and conduct maintenance on equipment, cleanup stained material and review self inspection processes.

Date: 10/11/2022

Corrective action date is the date the location was observed out of compliance.

Response: CA COMPLETED

Date of Completion: 10/25/2022

Operator Comment: Stained soil under and around generator removed and disposed of. Contractor discussion about zero spill expectations and spill prevention measures when filling generator fuel tanks.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

**2** CA# 165506

Corrective Action: Comply with Rule 606, which includes collecting all trash and debris that has blown off location.

Date: 10/11/2022

The corrective action date is the date the location was observed out of compliance.

Response: CA COMPLETED

Date of Completion: 10/25/2022

Operator Comment: Trash collected and properly disposed of. Contractors were told to ensure trash is not blown out of trash receptacles and ensure trash is placed in trash receptacles. See attached corrective action photo documentation.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

**3** CA# 165507

Corrective Action: Comply with Rule 606 and move or dispose of unnecessary equipment.

Date: 10/11/2022

Corrective action date is the date the location was observed out of compliance.

Response: CA COMPLETED

Date of Completion: 10/25/2022

Operator Comment: Fencing material removed from ditch and used to protect trenching. Pipes removed and used to build tank battery and facility flowlines.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Cugnetti

Signed: \_\_\_\_\_

Title: Director of EHSR

Date: 10/31/2022 12:51:43 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403213335	Corrective Action Photo Documentation
403213338	Corrective Action Photo Documentation
403213342	Corrective Action Photo Documentation
403213343	Corrective Action Photo Documentation
403213344	Corrective Action Photo Documentation
403213347	Corrective Action Photo Documentation

403213348	Corrective Action Photo Documentation
-----------	---------------------------------------

Total Attach: 7 Files